



Maritime and Coastguard Agency

MERCHANT SHIPPING NOTICE

MSN 1810 (M+F)

Radio Communications: SOLAS & non-SOLAS Vessels

Notice to all shipowners, fishing vessel owners, Builders, Masters and Officers, shore based maintenance providers, equipment manufacturers, classification societies and all other parties concerned.

This notice should be read with MSN1690 and replaces MSN 1779.

Summary

Key Notes:

1. This Notice specifies the changes in requirements for ships subject to SOLAS Chapter IV concerning radiocommunications which came into force on 1 July 2002 and Resolution MSC.152(78) which came into force 1 July 2006. It also applies to non-SOLAS vessels (e.g. Fishing Vessels > 15m) where the carriage of an EPIRB is mandatory.

2. The purpose of these guidelines is to:

- Establish standardised procedures and minimum levels of service for the testing and maintenance of satellite EPIRBs to ensure maximum reliability whilst minimising the risk of false distress alerting, including the adoption of Resolution MSC.152(78) in regard to SOLAS Chapter IV Regulation 15 – Maintenance requirements.
- To advise that all two-way communication equipment carried on board a ship which is capable of automatically including the ship's position in the distress alert shall be automatically provided with this information from an internal or external navigation receiver, if either is installed.

Introduction/ Background

1. With effect from 1 July 2002 a number of amendments to the International Convention for the Safety of Life at Sea 1974 (SOLAS) came into force concerning position updating of shipborne two-way communication equipment and the annual testing of satellite Emergency Position Indicating Radio Beacons (EPIRBs). Changes to SOLAS Chapter IV Regulation 15 entered into force through Resolution MSC.152(78) on 1 July 2006.

2. Subject to the following paragraphs and to the provisions of individual regulations in SOLAS Chapters IV and V, these amendments apply to ships as described in The Merchant Shipping (Radio Installation) Regulations 1998.

SOLAS CHAPTER IV REGULATION 15: Maintenance Requirements

3. The following new paragraph 9 has been added after existing paragraph 8: *Satellite EPIRBs shall be :*

.1 annually tested for all aspects of operational efficiency, with special emphasis on checking the emission on operational frequencies, coding and registration, at intervals as specified below:

.1 on passenger ships, within 3 months before the expiry date of the Passenger Ship Safety Certificate; and

.2 on cargo ships, within 3 months before the expiry date, or 3 months before or after the anniversary date, of the Cargo Ship Safety Radio Certificate.

The test may be conducted on board the ship or at an approved testing station; and

.2 subject to maintenance at intervals not exceeding five years, to be performed at an approved shore-based maintenance facility.

4. The Maritime Safety Committee has approved Guidelines for shore-based maintenance of satellite EPIRBs (see Annex 2). It should be noted that .12 of MSC 1040 requires maintenance by an approved shorebased maintenance provider. The UK Administration accepts organisations nominated and approved by the EPIRB manufacturer to carry out shorebased maintenance. Shorebased maintenance shall be carried out, in accordance with the requirements of MSC/Circ 1039 (reproduced in Annex 2), at an interval not exceeding five years or when battery replacement is due. For vessels where there is no mandatory EPIRB carriage requirement, the MCA would encourage owners to fit an EPIRB and conduct maintenance at a five year interval through an approved SBM where possible.

SOLAS CHAPTER IV REGULATION 18: Position Updating

5. The following new regulation 18 is added after existing regulation 17: *All two-way communication equipment carried on board a ship to which this chapter applies which is capable of automatically including the ship's position in the distress alert shall be automatically provided with this information from an internal or external navigation receiver, if either is installed. If such a receiver is not installed, the ship's position and the time at which the position was determined shall be manually updated at intervals not exceeding 4 h, while the ship is under way, so that it is always ready for transmission by the equipment.* Although there is provision for the circumstances where a navigation receiver is not installed, Regulation 19 2.1.6 of Chapter V of SOLAS requires from 1 July 2002 the carriage of a Global Navigation Satellite System receiver.

SOLAS CHAPTER IV REGULATION 13

6. Regulation 13 paragraph 8 requires a radio installation *including the navigation receiver referred to in regulation 18*, to have means provided *to ensure the continuous supply of such information in the event of failure of the ship's main or emergency source of electrical power.* Existing ships are also advised to ensure that equipment referred to in paragraph 6 above is connected to the ships Radio Reserve power supply.

More Information

Navigation Safety Branch
Maritime and Coastguard Agency
Bay 2/29
Spring Place
105 Commercial Road
Southampton
SO15 1EG

Tel : +44 (0) 23 8032 9146
Fax : +44 (0) 23 8032 9204
e-mail: Navigationsafety@mcga.gov.uk

General Inquiries: 24 Hour Infoline
infoline@mcga.gov.uk
0870 600 6505

MCA Website Address: www.mcga.gov.uk

File Ref: MNA 161/002/0019

Published: December 2006

© Crown Copyright 2006

Safer Lives, Safer Ships, Cleaner Seas

Printed on material containing minimum 75% post-consumer waste paper

*An executive agency of the
Department for
Transport*

GUIDELINES ON ANNUAL TESTING OF 406 MHz SATELLITE EPIRBs (MSC Circular 1040)

- 1 The annual testing of 406 MHz satellite EPIRBs is required by new SOLAS regulation IV/15.9 entering into force on 1 July 2002.
- 2 The testing should be carried out using suitable test equipment capable of performing all the relevant measurements required in these guidelines. All checks of electrical parameters should be performed in the self-test mode, if possible.
- 3 The examination of the installed 406 MHz satellite EPIRB should include:
 - .1 checking position and mounting for float-free operation;
 - .2 verifying the presence of a firmly attached lanyard in good condition; the lanyard should be neatly stowed, and must not be tied to the vessel or the mounting bracket;
 - .3 carrying out visual inspection for defects;
 - .4 carrying out the self-test routine;
 - .5 checking that the EPIRB identification (15 Hex ID and other required information) is clearly marked on the outside of the equipment;
 - .6 decoding the EPIRB 15 Hexadecimal Identification Digits (15 Hex ID) and other information from the transmitted signal, checking that the decoded information (15 Hex ID or MMSI/callsign data, as required by the Administration) is identical to the identification marked on the beacon;
 - .7 checking registration through documentation or through the point of contact associated with that country code;
 - .8 checking the battery expiry date;
 - .9 checking the hydrostatic release and its expiry date, as appropriate;
 - .10 checking the emission in the 406 MHz band using the self-test mode or an appropriate device to avoid transmission of a distress call to the satellites;
 - .11 if possible, checking emission on the 121.5 MHz frequency using the self-test mode or an appropriate device to avoid transmission of a distress call to the satellites;
 - .12 checking that the EPIRB has been maintained by an approved shore-based maintenance provider at intervals required by the Administration;
 - .13 after the test, remounting the EPIRB in its bracket, checking that no transmission has been started; and
 - .14 verifying the presence of beacon operations.

GUIDELINES FOR SHORE-BASED MAINTENANCE OF SATELLITE EPIRBs (MSC Circular 1039)

1 Introduction

- 1.1 The purpose of these guidelines is to establish standardised procedures and minimum levels of service for the testing and maintenance of satellite EPIRBs to ensure maximum reliability whilst minimising the risk of false distress alerting.
- 1.2 The guidelines are intended to be applicable both to 406 MHz EPIRBs and to L-band EPIRBs, as either type may be carried to comply with the requirements of SOLAS regulation IV/7.1.6. EPIRBs may include 121.5 MHz transmitters, or Global Navigation Satellite System (GNSS) receivers.
- 1.3 The guidelines also apply to service exchange EPIRBs which should be properly encoded to match the appropriate registration database.

2 Shore-based maintenance (SBM) provider

- 2.1 The SBM provider should:
 - .1 have a quality control system audited by a competent authority in respect of its servicing operation;
 - .2 have access to adequate calibrated test equipment and facilities to carry out the SBM in accordance with these guidelines;
 - .3 have access to batteries and other spare parts to the original equipment specification;
 - .4 have access to up-to-date technical manuals, service bulletins and the latest software versions as provided by the original equipment manufacturer;
 - .5 keep records of maintenance, available for inspection by the Administration as may be required;
 - .6 ensure that all personnel responsible for supervising and for carrying out the maintenance procedures are adequately trained and fully competent to perform their duties; and
 - .7 issue a shore-based maintenance report with a list of the test results and maintenance performed.

3 Prevention of false distress alerts

- 3.1 Throughout the testing and maintenance process, **great care must be taken to avoid the transmission of false distress alerts**. The transmissions may be picked up by aircraft as well as satellites.
- 3.2 A radio-frequency-screened room or enclosure should be used for all maintenance procedures involving, or likely to involve, any transmission from an EPIRB.
- 3.3 Provision of a 121.5 MHz monitor receiver is required; this will pick up the homing transmitter and give a warning if the EPIRB is accidentally activated outside the screened enclosure.

3.4 If a distress signal is transmitted accidentally, the local RCC should be contacted immediately and informed of the co-ordinates of the test site.

4 Maintenance service interval

4.1 406 MHz satellite EPIRBs should be inspected and tested in accordance with MSC/Circ.1040.

4.2 Shore-based maintenance of all satellite EPIRBs, as defined in paragraph 1.2, should be carried out in accordance with these guidelines at intervals specified by the flag Administration and not exceeding 5 years. It is recommended that the maintenance be performed at the time when the battery is to be changed.

5 Self-test

5.1 Prior to carrying out any maintenance and, upon completion, a self-test should be performed, following the instructions on the equipment, and the results noted.

5.2 Attention is drawn to paragraph 3 on the prevention of false distress alerts. Avoidance of live transmissions is required to prevent unnecessary loading of the satellite channels.

5.3 It should be verified that the self-test mode operates properly. This check could be performed by holding the switch in self-test mode position for 1 min after the first self-test mode burst transmission. All transmissions should cease after releasing the self-test mode switch. Additionally, for 406 MHz satellite EPIRBs which received the COSPAS-SARSAT type approval after October 1998 (Type Approval Certificates 106 and higher) the number of self-test bursts should be verified to be no more than one.

6 Battery change

6.1 The main battery should be changed in accordance with the manufacturer's recommendations, including the replacement of any other routine service parts (e.g. seals, memory battery, desiccant).

6.2 The removed batteries should be disposed of in accordance with the manufacturer's and/or national/local recommendations.

6.3 After having changed the battery, the new expiration date should be displayed on the exterior surface of the EPIRB.

7 Satellite distress transmission

7.1 The satellite EPIRB should be activated in its normal transmitting mode (i.e. not just self-test). Attention is drawn to paragraph 3 on the prevention of false distress alerts. Where seawater contacts are fitted, these should be connected together to activate the EPIRB.

7.2 The transmitted signal should be checked with a suitable test receiver to verify the signal integrity and coding.

7.3 The frequency of the transmitted signal should be recorded and verified to be within the limits required by the specification to which it is approved.

- 7.4 The output power of the transmitter should be checked in the self-test mode. A simple method of the emission verification, such as a low sensitivity receiver placed at an unobstructed distance of at least 3 m from the EPIRB antenna, may be used for this check. The original equipment manufacturer may suggest an appropriate method to verify the output power. Attention is drawn to paragraph 3 on the prevention of false distress alerts.

8 121.5 MHz homing transmission

- 8.1 The satellite EPIRB should be activated in its normal transmitting mode (i.e. not just self-test). Attention is drawn to paragraph 3 on the prevention of false distress alerts. Where seawater contacts are fitted, these should be connected together to activate the EPIRB.
- 8.2 The transmitted signal should be checked with a suitable test receiver for the characteristic swept tone modulation.

9 Global Navigation Satellite System (GNSS)

- 9.1 Some satellite EPIRBs are designed to transmit a position derived from a GNSS receiver, which may be internal or external to the EPIRB.
- 9.2 The original equipment (EPIRB) manufacturer should be consulted for a method of testing the correct operation of this function, e.g.: by using a GNSS repeater/simulator or external input. This test may involve a live transmission from the EPIRB and should be performed in a screened room or enclosure in accordance with paragraph 3.2. Attention is drawn to paragraph 3 on the prevention of false distress alerts.
- 9.3 A test receiver should be used to verify that the signal transmitted by the satellite EPIRB contains the correctly encoded position data derived from the GNSS receiver. Attention is drawn to paragraph 3 on the prevention of false distress alerts.

10 Waterproof integrity

- 10.1 The satellite EPIRB should be inspected for any signs of damage or cracks to the casing, or of water ingress. Any damaged item should be replaced in accordance with the manufacturer's recommended procedures.
- 10.2 The satellite EPIRB should be tested for waterproof integrity at the end of the SBM. The equipment manufacturer may suggest an appropriate method to test the integrity of the EPIRB.
- 10.3 One method involves immersing the equipment in hot water (20-30° C above ambient) for a period of 1 min. It can be readily seen if there are any problems with the seals, as the air inside the beacon expands and escapes as a stream of bubbles. This test should not be carried out with cool water, as the water may be drawn into the equipment without showing significant release of air bubbles.
- 10.4 Satellite EPIRBs equipped with seawater switches should have this function disabled during the immersion test to prevent activation, unless the complete test is performed inside a screened room. This disabling may be achieved by immersing the EPIRB complete with a mounting bracket if the bracket includes an interlock to prevent activation before release. In some cases the EPIRB contains an inversion switch, so it will not be activated if immersed in the inverted position. The manufacturer should be consulted for specific guidance.

11 Labelling

- 11.1 As a minimum, the equipment external labelling should be checked for the following details:
- .1 manufacturer's serial number. This identifies the equipment, even if the programmed data (e.g. MMSI or callsign) is later changed;
 - .2 the transmitted identification code: - for L – band EPIRBs, it will be the Inmarsat System Code; and – for 406 MHz EPIRBs, this will be the beacon 15 Hexadecimal Identification (15 Hex ID) and other encoded identification information (MMSI / callsign) as required by the Administration. It should be verified that the label matches the information decoded from the self-test mode transmission using the test receiver. For the COSPAS-SARSAT location protocol beacons, the 15 Hex ID should correspond to position data set to default values;
 - .3 the expiration date of the battery; and
 - .4 the date when the next shore-based maintenance is due (see paragraph 12.1).
- 11.2 The above checks also apply if a replacement EPIRB is provided by the SBM provider.

12 Shore-based maintenance report and other documentation

- 12.1 The results of shore-based maintenance should be provided in the form of a shore-based maintenance report, a copy of which is to be kept on board, and a label affixed to the exterior of the beacon detailing the name of the SBM provider and the date when the next shore-based maintenance is due.
- 12.2 The SBM provider may affix a tamperproof seal or similar device on completion of the SBM.
- 12.3 Before returning the beacon to the owner, or when providing a replacement beacon, the SBM provider should check the registration details with the beacon registry, where practicable.