

Instructions for Use

Scheduled and Out of Phase Maintenance Register Record - MOD Form 727E Forecast Log - Calendar - MOD Form 709A

Scheduled and Out of Phase Maintenance Register Record - MOD Form 727E

1. The Scheduled and Out of Phase Maintenance Register Record (SOOPMRR), is used to control all Out of Phase Maintenance activities. A 'Strike Off' facility permits the form to be used for both high and low frequency activities.
2. A high frequency sheet may be used to control all high frequency activities irrespective of Life Measurement Units.
3. If an item is extended, the 'Due at' column is to be struck through and the SNOW entered in the 'SNOW' column using RED INK. The revised "Due at" is then to be entered in the next 'Due at' column using RED INK.

Forecast Log - Calendar - MOD Form 709A

1. The Calendar Forecast Log covers a period of six months by individual days. This form may be used at the discretion of the local management through the Engineering Authority.