



MINISTRY OF DEFENCE

**Defence  
Infrastructure  
Organisation**

# POLICY INSTRUCTION

**Subject: Practitioners Guide 06/11 'Inspection of Airfield Pavements'**

**Number: PI 01/12**

DIO Sec Strategy & Policy Directorate Sponsor:

Ray Dickinson

Date of issue: 10 January 2012

Contact if different from above Sponsor:

John Cook  
Hd Airfield Pavements  
Professional & Technical Services  
Defence Infrastructure Organisation

[DIOOpsNorth-PTS5@mod.uk](mailto:DIOOpsNorth-PTS5@mod.uk)

(9)4421 2119 / 0121 311 2119

Who Should Read this:

CEstOs, Top Level Budget Holders, MOD Project Managers, SETLs & SEATs, Commanding Officers/Heads of Establishment, Defence Infrastructure Organisation (DIO) Deputy Heads (Estates), DIO Intl, DIO Advisors and Maintenance Management Organisations (MMO).

When it takes effect:

Immediately

When it is due to expire:

When superseded

Estate Management

## Equality And Diversity Impact Assessment

This policy has been Equality and Diversity Impact Assessed in accordance with the Department's Equality and Diversity Impact Assessment Tool against:

Part 1 Assessment Only (no diversity impact found)

### **Document Aim**

- 1.1 The aim of this Policy Instruction (PI) is to introduce Practitioners Guide 06/11 'Inspection of Airfield Pavements' and when it is applicable.
- 1.2 Airfield Inspections shall continue in their current format and current report format as per Technical Bulletin 00/14 (TB 00/14) until such time the airfield has been fully migrated and trained by DIO PTS Airfield Pavements Staff. At time of migration a MicroPAVER Database of the airfield will be issued to maintain and update as per the PG.  
  
*Note – It is not anticipated that migration to the new format will take place at airfields maintained under present Regional Prime contract arrangements until Next Generation Estate Contracts (NGEC) are in place.*
- 1.3 When fully migrated by DIO PTS staff; PG 06/11 will be the Mandatory lead document for Airfield Pavement Inspections that replaces the associated guidance contained in Technical Bulletin 00/14 (TB 00/14).

PG 06/11 can be found at:

[http://defencestates.cis.r.mil.uk/library/documents/Practitioner\\_guides/2011/11-06.pdf](http://defencestates.cis.r.mil.uk/library/documents/Practitioner_guides/2011/11-06.pdf)

[http://www.mod.uk/NR/ronlyres/FB4DE4DB-445B-423F-AC65-61CEF061E101/0/20111109PG06\\_11AirfieldInspectionsFinalU\\_2.pdf](http://www.mod.uk/NR/ronlyres/FB4DE4DB-445B-423F-AC65-61CEF061E101/0/20111109PG06_11AirfieldInspectionsFinalU_2.pdf)